

Repairs of KTP boxes for the automotive industry

www.ktpservis.cz



We perform renovations of plastic boxes for automotive – most often:

- KTP 114 777
- KTP 114 888
- KTP 114 999
- Furthermore, repairs of plastic pallets and lids

Workflow procedure for renovation of boxes:


- Surface preparation before repair – cleaning, degreasing
- Non-contact heating of the contact surfaces of parts using hot air
- Then the additive and base material are joined together using pressure

Workflow procedure for renovation of pallets:


- Surface preparation before repair – cleaning, degreasing
- Welding is done using same type of additive material
- The additive material is extruded into the welding zone under application of pressure

Examples of repairs:


(repaired areas marked in red)



Examples of repairs:




Examples of repairs:



Examples of repairs:



Examples of repairs:



Examples of repairs:



Examples of repairs: lid closure replacement



Examples of repairs: repair of missing lid

